




Attorney Docket No. 502639, Telephone (815) 963-7661


10



METHOD FOR MONITORING PROPER FASTENING OF
AN ARTICLE OF ASSEMBLY AT MORE THAN ONE LOCATION

Michael A. Walt, II and Samuel A. Walt

Attorney Docket No. 502639, Telephone (815) 963-7661



METHOD FOR MONITORING PROPER FASTENING OF
AN ARTICLE OF ASSEMBLY AT MORE THAN ONE LOCATION

Michael A. Walt, II and Samuel A. Walt

Attorney Docket No. 502639, Telephone (815) 963-7661





FIG. 5



METHOD FOR MONITORING PROPER FASTENING OF
AN ARTICLE OF ASSEMBLY AT MORE THAN ONE LOCATION

Michael A. Walt, II and Samuel A. Walt

Attorney Docket No. 502639, Telephone (815) 963-7661




FIG. 6




FIG. 7

